

BELZONA RESTORES BEARING HOUSING

ID: 304


Industry: *General Industry*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Construction Company in Florida, U.S.A.*
Application Date: *1985*

Substrate: *Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Large intermittent loads caused the bearing housing to become oblong and created a problem for the operator to effectively remove large buckets of earth.



Photograph Descriptions

- * Oversized bearing housing ,
- * Damage evident during trial fit ,
- * Cleaning off excess Belzona® 1111 ,
- * Finished application ,

Application Situation

Self aligning bearing housing for hydraulic ram controlling a bucket loader.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-7.

Belzona Facts

The construction company had a time clause contract and didn't have the luxury to weld or get a replacement part. The Belzona Consultant sold the job on Christmas Eve and got the call for the application a week later. The repair lasted for at least three years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve