

BELZONA TUBE SHEET AND END COVER REPAIR

ID: 31

Industry: Chemical & Petrochemical

Customer Location: Refinery in Alabama

Application: HEX-Heat Exchangers

Application Date: January 1996

Substrate: Steel

Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,

Problem

The tube bundle and end cover of a heat exchanger at a local refinery was badly eroded.



Photograph Descriptions

- * Eroded tube bundle prior to the repair ,
- * Repaired tube sheet ,
- * End cover rebuilt ,

Application Situation

Tube bundle and water box

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets HEX-1, HEX-2 and HEX-3.

Belzona Facts

All faces of the tube sheets were rebuilt using teflon and a steel plate as a former. The use of Belzona saved a replacement cost of approximately \$24,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve