

# FÖRDERBAND-REPARATUR MIT BELZONA

ID: 3361

Industrie: Leistung

Anwendung: Maschinen zur Handhabung von Feststoffen

Substrat: Gummi

Produkte: \* Belzona 2311 (SR Elastomer),

Standort des Kunden: Kraftwerk, Bulgarien

Antragsdatum: August 2002

## Problem

Durch einen mechanischen Schaden am Bandabstreicher wurde die Metallverstärkung freigelegt.



## Fotobeschreibungen

- \* 1. Ansicht der Förderanlage ,
- \* 2. Grundierung mit Belzona 2911 (Elastomer QD Conditioner) ,
- \* 3. Reparatur mit Belzona 2311 (SR Elastomer) ,

## Anwendungssituation

5 km langes Förderband für den Transport von Kohle zum Kraftwerk.

## Anwendungsverfahren

Die Anwendung wurde gemäß dem Belzona Know-how System Infoblatt SHM-1 durchgeführt.

## Belzona-Fakten

Für den Kunden war bei der Reparatur vor allem eine möglichst kurze Ausfallzeit entscheidend. Belzona wurde aufgrund seiner im Gegensatz zur Vulkanisation effektiven, einfachen und schnellen Anwendung ohne Spezialwerkzeuge gewählt.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

[www.belzona.com](http://www.belzona.com)

