# **BELZONA COATS PUMP BOWLS**

ID: 34

Industry: Power Plant in Mississippi

Application: CEP-Centrifugal Pumps Application Date: October 1995

Substrate: Cast iron

Products: \* Belzona® 1341 (Supermetalglide),

### Problem

Corrosion damage to the housing; power plant wanted to increase the efficiency of the pump.







# **Photograph Descriptions**

- \* The impeller,
- \* Application of Belzona® 1341 in progress,
- \* Two pump bowls coated,

# **Application Situation**

Two main cooling water pump bowls

# **Application Method**

The application was carried out in accordance with Belzona Know-How Leaflets CEP-3 and CEP-10.

### **Belzona Facts**

Belzona® 1341 (Supermetalglide) was chosen for its efficiency enhancement properties in fluid flow systems.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve