THORDON BEARING GLUED IN PLACE WITH BELZONA

ID: 3429

Industry: Power Customer Location: Hydro power station, Sweden

Application: SHM-Solids Handling Machinery Application Date: November 2008

Substrate: Cast iron

Products: * Belzona® 1321 (Ceramic S Metal),

Problem

The original bearing was worn out and in need of replacement. The client was looking for effective solution to bond the bearing in place.







Photograph Descriptions

- * Dismantling the bearing housing on the turbine,
- * The damaged bearing had disbonded from the bearing housing which resulted in a corroded surface,
- * Thordon SXL bearing half mounted and glued with Belzona® 1321. Clamps are used to hold bearing in position,

Application Situation

Replacement of one of the main turbine bearings.

Application Method

Application was carried out using a modified version of Belzona Know-How System Leaflet SHM-7. After grit blasting the bearing housing, Belzona® 1321 was applied to the bearing housing and Thordon SXL bearing before clamping into place until cured. Finally, the bearing was machined down to the correct inner diameter.

Belzona Facts

Thordon have worked closely with Belzona to ensure technical support is available for such applications. The Belzona® 1321 was chosen as adhesive based on its excellent adhesion, electrical insulation properties and its total corrosion resistance even in harsh environments. Belzona® 1321 is a well established method for bonding Thordon bearings and this technique has been reviewed and approved by the customer who are very pleased with the results.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com