

BELZONA BOAT LIFT TIRE REPAIR

ID: 35

Industry: *Marine*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Boat Repair Facility in Florida*
Application Date: *February 1996*

Substrate: *Rubber*
Products: ** Belzona® 2311 (SR Elastomer),*

Problem

Tires on lift are actually retreaded aircraft tires. Delamination of the tire tread due to use and exposure to the sun.



Photograph Descriptions

- * View of boat lift used to hoist vessels from water ,
- * Tire tread is separating from the tire ,
- * Tire repaired with Belzona® 2311 ,

Application Situation

Drydock boat lift tire

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet SHM-9.

Belzona Facts

Tires cost approximately \$1,000 each. Two units of Belzona® 2311 (SR Elastomer) were used to repair the damaged area and to

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

protect the tire from future deterioration. More importantly, it improved the reliability of the boat lift. If the machine is down, this company could be out of business.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

