

BELZONA ENHANCES THIS COAST GUARD CUTTER

ID: 351

Industry: Marine
Application: SOS-Ships and Offshore Structures

Customer Location: United States Coast Guard.
Application Date: September 2000

Substrate: Aluminum
Products: * Belzona® 1341 (Supermetalgilde),

Problem

The rudder and stabilizer assemblies suffer from cavitation and erosion from entrained solids.



Photograph Descriptions

- * View of the cutter ,
- * Application of Belzona® 1341 to stabilizers ,
- * Rudders coated ,
- * Completed application and equipment installed ,

Application Situation

110' Island Class Patrol boat rudder and stabilizer.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets SOS-1 and SOS-2.

Belzona Facts

All the stabilizer work was done in place. Two coats of Belzona® 1341 (Supermetalgilde) were applied and allowed to sufficiently cure. A small crane was then brought in and the equipment was then installed. Belzona® 1341 (Supermetalgilde) works well as long as the crew follows a regular cleaning procedure by periodically removing marine growth.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve