BELZONA TANK FARM

ID: 36

Industry: Chemical & Petrochemical Customer Location: Chemical Plant in South Alabama, USA

Application: TCC-Tanks and Chemical Containment Application Date: August 1995

Areas

Substrate: Concrete and Polymeric Concrete

Products: * Belzona® 4131 (Magma Screed),

* Belzona® 4311 (Magma CR-1),

Problem

Harsh chemicals attacking existing substrate which was installed in 1993.







Photograph Descriptions

- * View of damage to polymeric repair compound,
- * Application of Belzona® 4311 (Magma CR-1) in progress ,
- * 5000 sq. ft. area protected,

Application Situation

Chemical containment area (5000 sq. ft.)

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets TCC-9 and TCC-15.

Belzona Facts

The previous polymeric concrete repair material was damaged by chemical attack. The concrete was repaired and all areas protected.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®