

NEW BELZONA FLOOR SURFACE FOR WORKSHOP

ID: 364

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 4131 (Magma-Screed) ,*

Customer Location: *Engineering company in Portugal*
Application Date: *2002*

Problem

Previous floor coverings constantly failing and requiring regular maintenance. Floor cracked and generally in poor condition.



Photograph Descriptions

- * Belzona® 4911 (Magma TX Conditioner) being applied to ensure maximum adhesion ,
- * Application of Belzona® 4131 underway ,
- * Completed application ,
- * Another view of completed application ,

Application Situation

Floors in engineering workshop containing machine tools.

Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-1

Belzona Facts

Belzona® 4131 provides a tough impact and oil resistant surface.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve