

BELZONA GRIP SYSTEM MAINTAINS BRAKE TEST EQUIPMENT

ID: 3644

Industry: *General Industry*
Application: *SHM-Solids Handling Machinery*
Substrate: *Steel*
Products: ** Belzona® 1321 (Ceramic S-Metal) ,*

Customer Location: *Truck test centre, central Sweden*
Application Date: *February 2012 (it has been done regularly since 2002)*

Problem

The drive rollers in the brake tester lose their grip and do not have sufficient friction with the tyre to complete an accurate test.



Photograph Descriptions

- * Worn rollers in the truck tester ,
- * Close-up of the worn roller ,
- * Roller coated with Grip system of Belzona® 1321 and Silicon carbide aggregate, in the workshop ,
- * Finished application ,

Application Situation

Equipment for testing brake efficiency on trucks.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-12.

Belzona Facts

The customer is happy about the result and the lifetime, which is approximately 4 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

