

# BELZONA EMERGENCY IN A COOLING TOWER

ID: 37

Industry: *Power*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Concrete*  
Products: *\* Belzona® 3121 (MR-7) ,*

Customer Location: *Power Plant in Northwest Florida, USA*  
Application Date: *December 1996*

## Problem

*Crack (leak) in the containment wall and floor.*



## Photograph Descriptions

- \* The leak; sand bags used to hold back as much water as possible ,
- \* The completed repair ,

## Application Situation

Cooling tower containment

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-1.

## Belzona Facts

The repair was performed overnight and the plant was operational early the next morning. It is estimated that the plant saved \$6,000 in water cost alone.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve