

BELZONA EMERGENCY IN A COOLING TOWER

ID: 37

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: * Belzona® 3121 (MR-7),

Customer Location: Power Plant in Northwest Florida, USA
Application Date: December 1996

Problem

Crack (leak) in the containment wall and floor.



Photograph Descriptions

- * The leak; sand bags used to hold back as much water as possible ,
- * The completed repair ,

Application Situation

Cooling tower containment

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-1.

Belzona Facts

The repair was performed overnight and the plant was operational early the next morning. It is estimated that the plant saved \$6,000 in water cost alone.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve