

BELZONA AIR HANDLING FAN & SHROUD

ID: 373

Industry: General Industry

Customer Location: Steel Company - Hamilton, Ontario - Canada

Application: FBC-Fans, Blowers and Compressors

Application Date: May 2003

Substrate: Galvanized Steel

Products: * Belzona® 1341 (Supermetalglide) ,

Problem

Fan was constantly going out of balance due to particulate sticking to the blade.



Photograph Descriptions

- * Fan blasted to 3-4 mil profile, white metal finish ,
- * Second coat of Belzona® 1341 completed on fan ,
- * Shroud coat completed ,

Application Situation

Air Handling Fan

Application Method

The Application was carried out in accordance with Belzona Know-How System Leaflet FBC-2.

Belzona Facts

The fan was dynamically balanced before and after the application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve