

# BELZONA UPGRADES HOSPITAL ROOF

ID: 3866

Industry: *Buildings & Structures*

Application: *RPA-Roof Problem Areas*

Substrate: *New base layer Felt*

Products: *\* Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Hospital, UK*

Application Date: *April 2011*

## Problem

*This hospital roof required an insulation upgrade and in addition, weatherproofing to prevent any further damage.*



## Photograph Descriptions

- \* Insulation boards ready for installation on the deteriorated roof ,
- \* First coat of Belzona® 3111 applied ,
- \* Completed application ,

## Application Situation

Large hospital roof which had deteriorated through weathering

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8. After installing insulation boards overlaid with felt, a fully reinforced Belzona® 3111 system was applied.

## Belzona Facts

Since the application, the customer has saved on both heating and air conditioning costs and in addition, has reduced their carbon footprint.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve