

BELZONA SAFETY GRIP SYSTEM ON STAIRS

ID: 3879

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Steel*
Products: ** Belzona® 4411 (Granogrip) ,*

Customer Location: *Manufacturer, UK*
Application Date: *July 2012*

Problem

A potential slip hazard was identified on the metal stairs.



Photograph Descriptions

- * Steps before Belzona Application ,
- * Abraded and Masked steps ,
- * Half of steps completed ,
- * Completed application ,

Application Situation

Metal stairs leading to a mezanine floor area.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. After preparing the area with an MBX Bristle Blaster stripes of Belzona® 4411 red and yellow safety colours incorporating Belzona® 9221 aggregate were applied.

Belzona Facts

Belzona® 4411 gave a quick and easy solution to removing a slip hazard from a busy set of stairs. The non-slip properties of the

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona Grip system are ideal for this dusty environment and safety colours aide in both identifying the step edges and in highlighting the potential hazard.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

