

# BELZONA SAFETY GRIP SYSTEM ON STAIRS

ID: 3879

Industry: *General Industry*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Steel*  
Products: *\* Belzona® 4411 (Granogrip) ,*

Customer Location: *Manufacturer, UK*  
Application Date: *July 2012*

## Problem

*A potential slip hazard was identified on the metal stairs.*



## Photograph Descriptions

- \* Steps before Belzona Application ,
- \* Abraded and Masked steps ,
- \* Half of steps completed ,
- \* Completed application ,

## Application Situation

Metal stairs leading to a mezanine floor area.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. After preparing the area with an MBX Bristle Blaster stripes of Belzona® 4411 red and yellow safety colours incorporating Belzona® 9221 aggregate were applied.

## Belzona Facts

Belzona® 4411 gave a quick and easy solution to removing a slip hazard from a busy set of stairs. The non-slip properties of the

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

Belzona Grip system are ideal for this dusty environment and safety colours aide in both identifying the step edges and in highlighting the potential hazard.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

