

BELZONA PROVIDES SOLUTION TO LEAKING HOSPITAL ROOF

ID: 3885

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Mineral Felt*
Products: ** Belzona® 3131 (WG Membrane) ,*

Customer Location: *Hospital, Leeds, UK*
Application Date: *March 2011*

Problem

The felt roofing system had become porous over time and was allowing water into the building below. This was causing major disruption to the operation of the hospital as well as posing a health & safety risk.



Photograph Descriptions

- * Image of roof prior to application ,
- * Sealing around skylights and extraction unit ,
- * Completed application ,

Application Situation

Felt roof over physiotherapy facility within the hospital.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8. The entire roof was thoroughly cleaned to remove moss and lichens before applying a fully reinforced Belzona® 3131 System.

Belzona Facts

The Belzona solution was selected due to its ability to be applied in low temperatures. The client was looking for a cost effective solution which would cause no disruption to the operation of the hospital and without the need for hot works to be carried out.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve