

SLOPED SURFACE MADE SAFE WITH BELZONA

ID: 390

Industry: General Industry

Customer Location: Commercial Business Park in
Albuquerque, New Mexico U.S.A.

Application: FPA-Floor Problem Areas

Application Date: September 2001

Substrate: Concrete with exposed aggregate

Products: * Belzona® 4411 (Granogrip),

Problem

Sloped walkway with exposed aggregate became very slippery when wet, creating a safety hazard.



Photograph Descriptions

- * The slope walkway entrance was very slippery when wet. ,
- * The pattern is created as tape is being laid. ,
- * Application of the Belzona® Non-Slip System in progress. ,
- * The finished non-slip system; the pedestrian area is made safe. ,

Application Situation

Walkway entrance to office building.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

The non-slip system remains in perfect condition after several years. The potential for slippage is alleviated.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

