

# SLOPED SURFACE MADE SAFE WITH BELZONA

ID: 390

Industry: *General Industry*

Customer Location: *Commercial Business Park in  
Albuquerque, New Mexico U.S.A.*

Application: *FPA-Floor Problem Areas*

Application Date: *September 2001*

Substrate: *Concrete with exposed aggregate*

Products: *\* Belzona® 4411 (Granogrip) ,*

## Problem

*Sloped walkway with exposed aggregate became very slippery when wet, creating a safety hazard.*



## Photograph Descriptions

- \* The slope walkway entrance was very slippery when wet. ,
- \* The pattern is created as tape is being laid. ,
- \* Application of the Belzona® Non-Slip System in progress. ,
- \* The finished non-slip system; the pedestrian area is made safe. ,

## Application Situation

Walkway entrance to office building.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## Belzona Facts

The non-slip system remains in perfect condition after several years. The potential for slippage is alleviated.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve