

# CUSTOMER GOES NUTS OVER BELZONA FLOOR REPAIRS

ID: 394

Industry: *General Industry*

Customer Location: *Pecan Processing facility in Las Cruces,  
New Mexico U.S.A.*

Application: *FPA-Floor Problem Areas*

Application Date: *November 2001*

Substrate: *Concrete*

Products: *\* Belzona® 4131 (Magma-Screed) ,*

## Problem

*Epoxy overlay of concrete floor in processing plant was disbonded in many places.*



## Photograph Descriptions

- \* Cleaning. ,
- \* Surface preparation. ,
- \* Application. ,
- \* Finished. ,

## Application Situation

Factory Floor

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

The floor was soaked with pecan oil making the application very difficult. A detergent wash was used on the floor followed by an odorless degreaser followed by mechanical abrasion. This was followed by another degreasing. The pecan factory was so pleased with these initial repairs that they purchased additional material and continue to address other floor problem areas as they arise. After several years all repairs are holding up very well.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve