

BELZONA REPAIRS TO FLOATING HOSE

ID: 396

Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Oil Company
Application Date: December 1998

Substrate: Rubber
Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,
* Belzona® 2221 (MP Fluid Elastomer) ,

Problem

Extensive damage to the rubber flotation.



Photograph Descriptions

- * The extent of the damage clearly evident. ,
- * Application of Belzona® 2221. ,
- * Completed application. ,

Application Situation

24" Yokohama floating hose.

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

Belzona Facts

Inspected February 2000 hose still in good condition. Repair cost \$3,000; new hose cost about \$70,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve