SCHOOL BUILDING RESTORED WITH BELZONA

ID: 3974

Industry:	*Buildings & Structures*	Customer Location:	*Comprehensive School, South Wales*
Application:	*WPA-Wall Problem Areas*	Application Date:	*February 2012*
Substrate:	*Bath Stone & Brick Fascia*		
Products:	** Belzona 4141 (Magma Build) ,*		
	** Belzona 5122 (Clear Cladding Concentrate) ,*		

Problem

The stone work was weathering and the brick work was dirty. In addition there were areas suffering from rainwater ingress.

Photograph Descriptions

* Front of the school with damaged areas of concrete ,
* Damaged areas repaired with Belzona 4141 ,
* Application of Belzona 5122 ,
* Completed application ,

Application Situation

School building suffering for the effects of the weather

Application Method

Application was carried out in accordance with Belzona System Leaflets WPA-4 & 8. The Belzona 4141 was tinted with a cement tone additive to colour match the repair with the Bath Stone and to ensure a visually pleasing repair. The final stage of the application was to overcoat the surface with Belzona 5122.

Belzona Facts

Belzona completed the application to a high standard and the council responsible for the school was very pleased with the aesthetics of the repair application.

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

BELZONA® Repair • Protect • Improve

Copyright © Belzona International Limited 2024