

# BELZONA ELASTOMER REPAIR TO SEVERELY DAMAGED HOSE

ID: 398

Industry: *General Industry*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Dredging Company in Holland*  
Application Date: *October 1987*

Substrate: *Rubber*  
Products: *\* Belzona® 2111 (D & A Hi-Build Elastomer),*

## Problem

*Holes, cuts and tears in the rubber covers of five floating pipes.*



## Photograph Descriptions

- \* Typical tear in rubber pipe. ,
- \* Application of Belzona® 2111. ,
- \* Floating pipe in service with neoprene patch bonded with Belzona® 2111. ,

## Application Situation

Large diameter floating rubber pipes used in dredging.

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SOS-12.

## Belzona Facts

Belzona Elastomer repairs offer a rapid solution to torn and damaged floating hoses, at a fraction of the replacement cost. Additional strength was provided in some areas by bonding Neoprene rubber sheets over damaged areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve