

BELZONA ELASTOMER REPAIR TO SEVERELY DAMAGED HOSE

ID: 398

Industry: *General Industry*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Dredging Company in Holland*
Application Date: *October 1987*

Substrate: *Rubber*
Products: ** Belzona® 2111 (D & A Hi-Build Elastomer),*

Problem

Holes, cuts and tears in the rubber covers of five floating pipes.



Photograph Descriptions

- * Typical tear in rubber pipe. ,
- * Application of Belzona® 2111. ,
- * Floating pipe in service with neoprene patch bonded with Belzona® 2111. ,

Application Situation

Large diameter floating rubber pipes used in dredging.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SOS-12.

Belzona Facts

Belzona Elastomer repairs offer a rapid solution to torn and damaged floating hoses, at a fraction of the replacement cost. Additional strength was provided in some areas by bonding Neoprene rubber sheets over damaged areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve