

# BELZONA SOLVES DREDGE PUMP WOES

ID: 40

Industry: Marine

Customer Location: Marine contractor, Panama City, Florida, U.S.A.

Application: CEP-Centrifugal Pumps

Application Date: August 1999

Substrate: Rubber

Products: \* Belzona® 2311 (SR-Elastomer),

## Problem

Large roots and stones damaged cutwater and stripped rubber coating from pump.



## Photograph Descriptions

- \* The damage ,
- \* Completed repair ,
- \* Dredge pump ready for service ,

## Application Situation

Dredge pump repair.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet CEP-1.

## Belzona Facts

Application proceeded rapidly using Belzona® 2311 (SR-Elastomer) to achieve full mechanical properties in less than two hours with minimal downtime for the dredge pump operator.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve