

Belzona repairs damaged pre-heater fan shaft

ID: 4024

Industry: General Industry
Application: MPT-Mechanical Power Transmission

Customer Location: Egypt
Application Date: 2008

Substrate: Steel
Products: * Belzona 1111 (Super metal) ,

Problem

The shaft was worn out under the bearing.



Photograph Descriptions

- * 1. The damaged equipment ,
- * 2. The damaged area ,
- * 3. The application before removal of formers ,
- * 4. The completed application ,

Application Situation

Worn shaft

Application Method

This application was carried out in accordance with MPT-2. The shaft can be returned to its original dimensions by using released split formers. These can easily be removed once the product has cured to reveal a perfect finish.

Belzona Facts

Conventional repair methods would be very time consuming and would be much more expensive. The Belzona solution however reduces this downtime to a fraction of the time and cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve