

# Belzona provides internal corrosive resistant lining

ID: 4041

Industry: Oil & Gas  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Carbon Steel  
Products: \* Belzona 5811 (Immersion Grade),

Customer Location: Egypt  
Application Date: March 2006

## Problem

Corrosion occurring on the internal surfaces which needed to be protected.



## Photograph Descriptions

- \* 1. Corrosion Damage ,
- \* 2. 1st coat successfully applied ,
- \* 3. 2nd coat application ,
- \* 4. Completed application ,

## Application Situation

Media filter requiring internal lining

## Application Method

The repair was carried out in accordance with TCC-3. The two different coloured coats of Belzona 5811 were applied to avoid any pinholes or misses.

## Belzona Facts

Belzona 5811 can be spray applied therefore larger applications can be completed quicker.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve