

BELZONA PROTECTION INSIDE AND OUT!

ID: 406

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon Steel
Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 4311 (Magma CR-1) ,
* Belzona® 4341 (Magma CR-4) ,
* Belzona® 5111 (Ceramic Cladding) ,
* Belzona® 6111 (Liquid Anode) ,

Customer Location: Oil Company - Mexico
Application Date: December 2003

Problem

Internal corrosion due to contact with HCL (hydrochloric acid) 30-36% had caused severe corrosion on the walls, nozzles, fittings, etc. of the tanks. The exterior of the tanks had been damaged from atmospheric corrosion.



Photograph Descriptions

- * Extent of the corrosion due to the effects of the hydrochloric acid coupled with hydrocarbons and heat. ,
- * Nozzles coated with Belzona® 4311 or Belzona® 4341, depending on operating temperatures. ,
- * Pinhole detection being carried out over the Belzona coating system. ,
- * Exterior view of the tank coated on the outside with Belzona® 6111/Belzona® 5111. ,

Application Situation

Portable Acid Tanks for Oil Well Injection.

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

Belzona Facts

Failure of vinyl ester coating forced customer to bring the tanks out of operation every 4-6 months. The Belzona solution allowed for the rebuilding of the damaged areas with Belzona® 1111. Depending on the operation temperatures of the tanks, either Belzona®

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

4311 or Belzona® 4341 was used as the coating material. Belzona® 6111/5111 was used on the exterior of the tanks.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

