

BELZONA PROTECTS COOLING WATER SPOOLS

ID: 410

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Steel
Products: * Belzona® 1341 (Supermetalglide) ,

Customer Location: Power station - Ireland
Application Date: 2003

Problem

Previous coating was badly damaged allowing severe erosion-corrosion on pipework internals.



Photograph Descriptions

- * General view of the spools ,
- * Degree of original erosion clearly evident ,
- * Application underway ,
- * Completed application ,

Application Situation

Main cooling water intake pipework.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

Belzona Facts

Some spools were so badly corroded that they had to be replaced or sleeved. The Belzona® 1341 coating will prevent future costly replacement becoming necessary.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve