

BELZONA CREATES SAFE ENTRANCE FOR WORKERS AND VISITORS

ID: 4175

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Quarry tile
Products: * Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Building materials manufacturer, Croatia
Application Date: October, 2012.

Problem

New quarry tiled floor at the entrance to the factory reception was extremely slippery when wet. This identified slip hazard had to be made good by the client.



Photograph Descriptions

- * New quarry tiles that are very slippery when wet ,
- * Application in progress - creation of pattern ,
- * Application finished ,
- * Application finished - close up shot ,

Application Situation

Main entrance to the factory. All staff and visitors pass through this area on their way in and out of the factory.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona provided an acceptable and cost effective solution. Application was carried out late in the evening, in order not to disturb customers during his operating hours. In the morning the floor was ready. Belzona solution eliminated the trip hazard and provided durable and nice-looking non-slip system. The expensive alternative was to replace the quarry tiles.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

