

BELZONA RESTORES TUBE SHEET PROTECTION


ID: 4197

Industry: Power
Application: HEX-Heat Exchangers
Substrate: Carbon Steel
Products: * Belzona 1321 (Ceramic S Metal) ,

Customer Location: Power station, Cairo, Egypt
Application Date: September 2003

Problem

Original coating on tube sheet had failed. Replacement required to prevent future corrosion.



Photograph Descriptions

- * Damaged original coating ,
- * After surface preparation ,
- * First coat of Belzona® 1321 applied ,
- * Second coat of Belzona 1321 applied ,

Application Situation

condenser Tube Sheet

Application Method

The application was carried out in accordance with Belzona System Leaflet HEX-3.

Belzona Facts

The Belzona repair was carried out quickly, minimizing outage time. Belzona® 1321 has a long track record of providing corrosion protection on such equipment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve