

# SOAP POWDER CAN'T WASH BELZONA AWAY!

ID: 420

**Industry:** General Industry

**Customer Location:** Manufacturer of washing powder in Italy

**Application:** TCC-Tanks and Chemical Containment Areas


**Application Date:** On-going since 2002

**Substrate:** Cast Steel

**Products:** \* Belzona® 4311 (Magma CR1) ,

## Problem

Corrosion from the soap powder and water mixture damages the housing and rotating elements of the mixer.



## Photograph Descriptions

- \* The mixer as it arrives ,
- \* The coated rotating elements ,
- \* The mixer end covers coated ,
- \* The mixer body coated ,

## Application Situation

Soap Mixer

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

## Belzona Facts

The customer is pleased with the performance of the Belzona coating and there is an on-going program to protect these mixers.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2024

  
**BELZONA®**  
Repair • Protect • Improve