

Belzona Rebuilds and Protects Fans

ID: 4200

Industry: *Fluid Flow*
Application: *FBC-Fans, Blowers and Compressors*

Customer Location: *Sharkeya, Egypt*
Application Date: *May 2006*

Substrate: *Cast Iron*
Products: ** Belzona 1311 (Ceramic R Metal) ,*
** Belzona 1321 (Ceramic S Metal) ,*

Problem

Belzona was required to rebuild and protect damaged fan blades



Photograph Descriptions

- * 1. Before application ,
- * 2. Belzona 1311 application ,
- * 3. Belzona 1321 application ,
- * 4. Completed application ,

Application Situation

Fan blades

Application Method

The application was carried out in accordance with Belzona Know How System Leaflets FBC-1 and FBC-2.

Belzona Facts

The Belzona solution will provide a corrosion and erosion resistant coating for long term protection.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve