

Belzona Rebuilds and Protects Cavitated Fan Vanes

ID: 4202

Industry: *Fluid Flow*
Application: *FBC-Fans, Blowers and Compressors*

Customer Location: *Talkha, Egypt*
Application Date: *October 2006*

Substrate: *Cast Iron*
Products: ** Belzona 1311 (Ceramic R Metal) ,*
** Belzona 1321 (Ceramic S Metal) ,*

Problem

The fan blades were suffering from the effects of cavitation damage.



Photograph Descriptions

- * 1. Damaged Fan Blades ,
- * 2. Belzona 1311 application ,
- * 3. First coat application of Belzona 1321 ,
- * 4. Second coat application of Belzona 1321 ,

Application Situation

Fan Vanes

Application Method

The application was carried out in accordance with FBC-1 and FBC-2.

Belzona Facts

Belzona is able to rebuild and protect the fan vanes with a quick and easy solution. In areas where the vanes are completely eroded metal plates can be positioned into the system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve