

# BELZONA® 3211 (LAGSEAL) IN TOUGH ENVIRONMENT - 2ND TIME AROUND

ID: 423

Industry: Power  
Application: TCC-Tanks and Chemical Containment Areas

Customer Location: Power plant in Texas, USA  
Application Date: 2004

Substrate: Foam insulation over plastic tank  
Products: \* Belzona® 3211 (Lagseal) ,  
\* Belzona® 3921 (GSC Surface Conditioner) ,  
\* Belzona® 9311 (Reinforcing Membrane Sheet) ,

## Problem

After eight years of service the previously applied Belzona® 3211 (Lagseal) was ready for replacement. The Belzona Membrane System performed so well in its first eight years, the customer naturally chose Belzona again.



## Photograph Descriptions

- \* View from acid tank ,
- \* Surface preparation ,
- \* Belzona® 3211 applied ,

## Application Situation

Coating on insulated caustic storage tank

## Application Method

Once the old coating was removed, the application proceeded in accordance with Belzona® Know-How System Leaflet TCC-4.

## Belzona Facts

Belzona® 3211 held up well (eight years) in this tough environment. Fumes from neighboring acid tank condensed on a tank, causing rapid deterioration of the previous coatings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve