

BELZONA® 3211 (LAGSEAL) IN TOUGH ENVIRONMENT - 2ND TIME AROUND

ID: 423

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas

Customer Location: Power plant in Texas, USA
Application Date: 2004

Substrate: Foam insulation over plastic tank
Products: * Belzona® 3211 (Lagseal) ,
* Belzona® 3921 (GSC Surface Conditioner) ,
* Belzona® 9311 (Reinforcing Membrane Sheet) ,

Problem

After eight years of service the previously applied Belzona® 3211 (Lagseal) was ready for replacement. The Belzona Membrane System performed so well in its first eight years, the customer naturally chose Belzona again.



Photograph Descriptions

- * View from acid tank ,
- * Surface preparation ,
- * Belzona® 3211 applied ,

Application Situation

Coating on insulated caustic storage tank

Application Method

Once the old coating was removed, the application proceeded in accordance with Belzona® Know-How System Leaflet TCC-4.

Belzona Facts

Belzona® 3211 held up well (eight years) in this tough environment. Fumes from neighboring acid tank condensed on a tank, causing rapid deterioration of the previous coatings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve