

BELZONA REPAIR STILL IN PLACE AFTER NINE YEARS & MILLIONS OF PASSOVERS

ID: 429

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 4111 (Magma-Quartz) ,*
** Belzona® 4131 (Magma-Screed) ,*

Customer Location: *Missouri Department of Transport - USA*
Application Date: *August 1994*

Problem

Patching with asphalt is temporary, other products were not staying in place, causing safety concerns. A four hour timeframe is the longest allowed for lane shutdown.



Photograph Descriptions

- * Final stages of surface preparation ,
- * Belzona® 4131 down; ready for next phase ,
- * Belzona® 4111 applied ,
- * External heat apparatus to speed up the lane opening ,

Application Situation

Big pothole in busy concrete interstate highway.

Application Method

The application is carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-1.

Belzona Facts

This nine-year-old application is on the busiest stretch of interstate in the state of Missouri - linking St. Louis with Kansas City. The ragged edges and spalled concrete were cut out. Belzona® 4131 was used to fill in the hole, topped off with 1/4"-inch of Belzona® 4111. The application area was then covered with concrete blankets and heated with a gas-fired portable heater. External heat was applied for 50 minutes at 180°F, allowing the lane to open less than four hours later. It's still there today.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

