

BELZONA LAP JOINT REPAIR AT SAWMILL

ID: 44

Industry: *Pulp & Paper*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Sawmill in Ontario, Canada*

Application Date: *June 1994*

Substrate: *Rubber*

Products: ** Belzona® 2111 (D&A Hi-Build Elastomer),*

Problem

Fine pieces of veneer and moisture contributed to joint deterioration and failure within a matter of a few weeks.



Photograph Descriptions

- * Delaminated lap joint being prepared for the Belzona application ,
- * Both halves of the belt were coated with Belzona® 2111 ,
- * The lap joint bonded together for a long lasting, durable, in-place repair ,

Application Situation

Conveyor belt that transfers pieces of veneer to the chipper.

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SHM-3.

Belzona Facts

The customer now uses Belzona to bond the joints of the belt which lasts approximately six months, instead of a matter of weeks.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve