

LEAKY ROOF IS NO PROBLEM FOR BELZONA


ID: 443

Industry: General Industry
Application: RPA-Roof Problem Areas
Substrate: Galvanized steel
Products: * Belzona® 3111 (Flexible Membrane) ,
* Belzona® 3921 (GSC Surface Conditioner) ,
* Belzona® 9311 (Reinforcing Membrane Sheets) ,

Customer Location: Factory roof - Texas U.S.A.
Application Date: 2001 thru 2004

Problem

Galvanized roof had numerous leaks around gutters. Previous attempts to stop leaks with conventional roofing materials failed.



Photograph Descriptions

- * Conditioned and coated ,
- * Roof gutters ,
- * View of roof area ,
- * Another view of the gutters ,

Application Situation

Sections of roof gutters

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

Belzona Facts

Areas were cleaned, conditioned and two coats of Belzona® 3111 were brushed on. The total area protected with Belzona® 3111 was 8,000 sq. ft.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve