

BELZONA REPAIRS MASSIVE FAILURE OF KILN SUPPORT CASINGS

ID: 447

Industry: *Cement*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona® 1111 (Super Metal) ,*

Customer Location: *Cement works in Egypt*
Application Date: *March 2004*

Problem

Casings on trunnion supports shattered due to the breakage of the roller neck.



Photograph Descriptions

- * General view of the trunnion supports ,
- * The shattered casings ,
- * One of the fabricated strengthening plates in position ,
- * Belzona® 1111 used to bond and seal the cracked casing ,

Application Situation

Rotary kiln used in cement production

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

Belzona Facts

Various strengthening plates and straps were used to add strength to the repairs. Two large casings were completely restored. Alternative was the replacement at the cost of \$20,000 each and six months delivery time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve