

# BELZONA REPAIRS MASSIVE FAILURE OF KILN SUPPORT CASINGS

ID: 447

Industry: Cement  
Application: ENC-Engines and Casings  
Substrate: Cast Iron  
Products: \* Belzona® 1111 (Super Metal) ,

Customer Location: Cement works in Egypt  
Application Date: March 2004

## Problem

Casings on trunnion supports shattered due to the breakage of the roller neck.



## Photograph Descriptions

- \* General view of the trunnion supports ,
- \* The shattered casings ,
- \* One of the fabricated strengthening plates in position ,
- \* Belzona® 1111 used to bond and seal the cracked casing ,

## Application Situation

Rotary kiln used in cement production

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

## Belzona Facts

Various strengthening plates and straps were used to add strength to the repairs. Two large casings were completely restored. Alternative was the replacement at the cost of \$20,000 each and six months delivery time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve