

BELZONA EMERGENCY LEAK SEALING: THREE HOURS LATER - IT'S READY

ID: 450

Industry: *General Industry*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Carbon steel*
Products: ** Belzona® 1111 (Super Metal) ,
* Belzona® 1291 (ES Metal) ,*

Customer Location: *Fertilizer producer in Egypt*
Application Date: *October 2003*

Problem

Corrosion of vessel had caused leak.



Photograph Descriptions

- * Belzona® 1291 used in conjunction with metal clamp to initially stem the leak ,
- * Belzona® 1111 plus Belzona® 9341 (Reinforcement Tape) applied to strengthen the repair ,
- * Repair completed in 3 hours ,

Application Situation

Natural gas separator operating at 43 bar pressure

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

Belzona Facts

Belzona® 1291 was initially used in conjunction with a metal clamp to stem the leak before applying Belzona® 1111 with Belzona® 9341 (Reinforcement Tape) to complete the application. Repair completed quickly and safely without heat so preventing the need for a major plant shut-down.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve