WATERPROOFING CHIME ANGLE WITH BELZONA

ID: 460

Industry: Power Customer Location: Power Plant - Texas USA

Application: GSS-Gaskets, Seals and Shims Application Date: May 2004

Substrate: Steel and concrete

Products: * Belzona® 3111 (Flexible Membrane),

* Belzona® 3921 (PSC Surface Conditioner),

* Belzona® 9311 (Membrane Reinforcing Sheet),

Problem

Corrosion was occuring on steel/concrete interface of wastewater tank and pad.









Photograph Descriptions

- * Close look at the problem area,
- * Prepared surface taped off,
- * Application completed,

Application Situation

Tank Chime Angle

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3.

Belzona Facts

Customer had used Belzona® 3111 on many other water proofing repairs. Numerous attempts using caulking materials did not stand up to the requirements.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are FS 695214 manufactured under an ISO ISO 14001:2015 9000 Registered Quality EMS 695213 Management System.