

# BELZONA SEALS LEAKING MUSIC ROOM ROOF

ID: 4630

Industry: Buildings & Structures

Customer Location: Prestigious boarding school, Somerset, England

Application: RPA-Roof Problem Areas

Application Date: August, 2012

Substrate: Bitumen

Products: \* Belzona 3131 (WG Membrane),

## Problem

Breakdown of the old bituminous substrate had allowed multiple area's of water ingress causing damage to the fabric of the building & creating health and safety issues. Due to it's location adjoining a listed school building a hot applied system was not acceptable.



## Photograph Descriptions

- \* Close up of previous repairs which had failed ,
- \* Preparation of the roof by removing loose chippings ,
- \* First coat of Belzona 3131 being applied with reinforcement sheet ,
- \* Completed application several months later ,

## Application Situation

Roof over the music room at a prestigious private school

## Application Method

The application was carried out in strict accordance with Belzona System leaflet RPA-1.

## Belzona Facts

The Belzona solution being cold curing, combined with its ease of application and ability to seal the various roof details met the clients requirements.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve