

KITCHEN SAFETY IMPROVED THANKS TO BELZONA

ID: 465

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Quarry tiles*
Products: ** Belzona® 5231 (SG Laminate) ,*

Customer Location: *School in UK*
Application Date: *July 2002*

Problem

Routine health inspection had highlighted hygiene and safety problems with the floor area necessitating refurbishment before the school re-opened.



Photograph Descriptions

- * Kitchen area prior to the Belzona application ,
- * Wash area prior to the Belzona application ,
- * Belzona® 5231 applied ,
- * Application completed ,

Application Situation

Floors in kitchen area

Application Method

Two coats of Belzona® 5231 were applied after thoroughly cleaning and grit blasting the existing tiled surface.

Belzona Facts

Belzona® 5231 created a hygienic, seamless floor surface with the right degree of non-slip to provide safe footing for the kitchen staff. The application was completed smoothly in the short holiday period during which the school was closed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve