

# BELZONA REPAIR TO LOADER TYRE SIDEWALL

ID: 4669

Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Quarry in Croatia*  
Application Date: *April, 2013.*

Substrate: *Rubber*  
Products: *\* Belzona 2211 (MP Hi-Build Elastomer) ,*

## Problem

*There was a large crack in a tyre, but it was not leaking and the steel reinforcement was still in good shape. Customer needed to keep the loader in operation.*



## Photograph Descriptions

- \* Damaged tyre on wheel loader ,
- \* Application in progress ,
- \* Application finished ,
- \* Site revisited after 3 months, the tyre is still in perfect shape ,

## Application Situation

The loader works in a remotely located quarry. It is used on two shifts per day. The customer needed quick in-situ repair.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

## Belzona Facts

The two alternatives were either to replace the tyre or to dismantle it and transport it to the nearest workshop. Belzona repair was carried out during the weekend and customer didn't lose any production time. The Belzona repair prevented further deterioration of the tyre and was performing well when expected three months later.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve