

# RUBBER TRACKS ON MOBILE DRILLING RIG QUICKLY REPAIRED WITH BELZONA

ID: 4683

Industry: *General Industry*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Geotechnical survey company, Croatia*  
Application Date: *September, 2013.*

Substrate: *Rubber*  
Products: *\* Belzona 2311 (SR Elastomer) ,*

## Problem

*Several damaged areas on its rubberized tracks required quick repair to prevent track failure.*



## Photograph Descriptions

- \* Geo drilling machine on site ,
- \* One of the damaged areas on the tracks ,
- \* Damaged area after surface preparation and Conditioning ,
- \* Application finished. ,

## Application Situation

Mobile Geotechnical drilling machine operating two shifts per day.

## Application Method

The application was carried out in accordance with Belzona System Leaflet SHM-1.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

## Belzona Facts

The only alternative was to remove the machine from the building site to the workshop, which would cause downtime and delay to the operator. Belzona team did the repair within few hours' time and the machine was back in service the same day. Cost savings were significant in comparison to alternative.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

