

CLARIFIER TROUGHS RESTORED WITH BELZONA

ID: 4685

Industry: Water / Wastewater

Customer Location: Water treatment facility, Roseville, California

Application: TCC-Tanks and Chemical Containment Areas

Application Date: September 2003

Substrate: Concrete

Products: * Belzona® 5811 (Immersion Grade),

Problem

Concrete clarifier troughs had deteriorated to point of exposing the aggregate in the concrete.



Photograph Descriptions

- * Clarifier trough before application - overview ,
- * Clarifier trough before application - detail ,
- * Belzona® 5811 application ,
- * Clarifier trough In operation after coating ,

Application Situation

Effluent clarifier unit.

Application Method

Application was carried out in accordance with Belzona Know-How system Leaflet TCC-15.

Belzona Facts

Belzona® 5811 coating eliminated need for costly replacement of concrete clarifier troughs. Based on the success of this application, customer not only applied Belzona to a second clarifier but also specified Belzona® 5811 for all immersed metals for their new and much larger additional wastewater facility.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve