

# BALCONIES WATERPROOFED WITH BELZONA


ID: 4691

Industry: Buildings & Structures  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Concrete  
Products: \* Belzona® 5811 (Immersion Grade),

Customer Location: Boutique Hotel, London  
Application Date: June 2013

## Problem

The aging balconies had numerous fine cracks and the hotel had been suffering from water penetration issues. With high occupancy rates a quick turnaround was essential.



## Photograph Descriptions

- \* Unprotected balconies ,
- \* Contractor carrying out application ,
- \* & 4. Completed work ,

## Application Situation

Balconies on Victorian era hotel

## Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-15. the Belzona 5811 was applied using brushes and squeegees.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

Due to the products solvent free properties the contractor was able to complete the application very quickly and without any disruption to the hotel guests. The standard grey colour also complemented the existing colour scheme on the exterior of the hotel. As the balconies don't get used there was no need for a grip system.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

