

BALCONIES WATERPROOFED WITH BELZONA

ID: 4691

Industry: Buildings & Structures
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: * Belzona® 5811 (Immersion Grade),

Customer Location: Boutique Hotel, London
Application Date: June 2013

Problem

The aging balconies had numerous fine cracks and the hotel had been suffering from water penetration issues. With high occupancy rates a quick turnaround was essential.



Photograph Descriptions

- * Unprotected balconies ,
- * Contractor carrying out application ,
- * & 4. Completed work ,

Application Situation

Balconies on Victorian era hotel

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-15. the Belzona 5811 was applied using brushes and squeegees.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Due to the products solvent free properties the contractor was able to complete the application very quickly and without any disruption to the hotel guests. The standard grey colour also complemented the existing colour scheme on the exterior of the hotel. As the balconies don't get used there was no need for a grip system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

